

*Hong Kong Exchanges and Clearing Limited and The Stock Exchange of Hong Kong Limited take no responsibility for the contents of this announcement, make no representation as to its accuracy or completeness and expressly disclaim any liability whatsoever for any loss howsoever arising from or in reliance upon the whole or any part of the contents of this announcement.*



## **CHINA GOLD INTERNATIONAL RESOURCES CORP. LTD.**

### **中國黃金國際資源有限公司**

*(a company incorporated under the laws of British Columbia, Canada with limited liability)*

(Hong Kong Stock Code: 2099)

(Toronto Stock Code: CGG)

### **Overseas Regulatory Announcement**

**VANCOUVER, March 31, 2023** – China Gold International Resources Corp. Ltd. (TSX: CGG; HKEX: 2099) (“**China Gold International Resources**” or the “**Company**” ) reports that production has been suspended at its Jiama Copper-Gold Polymetallic Mine (“**Jiama Mine**”) due to a tailings overflow.

Please see the attached announcement for details.

By order of the Board

**China Gold International Resources Corp. Ltd.**

**Mr. Junhu Tong**

Chairman and Chief Executive Officer

Hong Kong, 31 March 2023

*As at the date of this announcement, the Board of Directors of the Company comprises of Mr. Junhu Tong, Mr. Yuanhui Fu, Mr. Weibin Zhang, Ms. Na Tian as Executive Directors, Mr. Wanming Wang as Non-Executive Director, and Mr. Y.B. Ian He, Mr. Wei Shao, Ms. Ruixia (Rane) Han and Mr. Bielin Shi as Independent Non - Executive Directors.*



## China Gold International Resources Reports Tailings Overflow at Its Jiama Copper-Gold Polymetallic Mine

VANCOUVER, March 31, 2023 – China Gold International Resources Corp. Ltd. (TSX: CGG; HKEX: 2099) (“**China Gold International Resources**” or the “**Company**”) reports that production has been suspended at its Jiama Copper-Gold Polymetallic Mine (“**Jiama Mine**”) due to a tailings overflow.

On March 27, 2023, a tailings overflow occurred due to minor tailing dam damages from the Guolanggou tailings pond at the Company's Jiama Mine. The Company immediately launched an emergency plan to assess and contain the overflow. Production operations were suspended and non-essential personnel were evacuated from the affected area. The Company was able to quickly contain and repair the damage while ensuring the safety of people and the environment. With the repair of Guolanggou tailings dam, the overflow has been contained. In addition, the Slope monitoring radar has been installed to monitor the starter dyke and subsequent dykes of the tailing pond on a 24-hour basis.

The tailings overflow did not cause any contamination to the surrounding environment, and there was no impact on the safety of employees and local community. Under the supervision and guidance of the emergency management and mine safety supervision departments, the Company is currently conducting a comprehensive risk assessment of the tailings pond, developing and implementing a restoration plan to ensure the safety of the tailings pond.

### **About China Gold International Resources**

China Gold International Resources is a gold and base metal mining company incorporated in BC, Canada and operates two mines, the Chang Shan Hao Gold Mine in Inner Mongolia, China and the Jiama Copper-Gold Polymetallic Mine in Tibet, China. The Company's objective is to build shareholder value through growing production at its current mining operations, expanding its resource base, and acquiring and developing new projects internationally. The Company is listed on the Toronto Stock Exchange (TSX: CGG) and the Main Board of The Stock Exchange of Hong Kong Limited (HKEX: 2099).

For further information on the Company, please refer to SEDAR's website at [www.sedar.com](http://www.sedar.com), The Stock Exchange of Hong Kong Limited's website at [www.hkex.com.hk](http://www.hkex.com.hk), the Company's website at [www.chinagoldintl.com](http://www.chinagoldintl.com), or call the Company at +1-604-609-0598 and email to [info@chinagoldintl.com](mailto:info@chinagoldintl.com).

### **Cautionary Note About Forward-Looking Statements**

*Certain information regarding China Gold International Resources contained herein may constitute forward-looking statements within the meaning of applicable securities laws. Forward-looking statements may include estimates, plans, expectations, opinions, forecasts, projections, guidance or other statements that are not statements of fact. Although China Gold International Resources believes that the expectations reflected in such forward-looking statements are reasonable, it can give no assurance that such expectations will prove to have been correct. China Gold International Resources cautions that actual*



# China Gold International Resources Corp. Ltd.

Suite 660, One Bentall Centre  
505 Burrard Street  
Vancouver, BC  
Canada V7X 1M4

---

*performance will be affected by a number of factors, most of which are beyond its control, and that future events and results may vary substantially from what China Gold International Resources currently foresees. Factors that could cause actual results to differ materially from those in forward-looking statements include market prices, exploitation and exploration results, continued availability of capital and financing and general economic, market or business conditions. The forward-looking statements are expressly qualified in their entirety by this cautionary statement. The information contained herein is stated as of the current date and subject to change after that date.*